Make: Next Gen Model: Blackline

Registration (REGO): 918 81B VIN: 6K9NEXTGEJC289375

Chassis Number: N01160 Year: 2018



CONDITION REPORT

	Туре	Comments
Manager's comments		A good looking van from the outside, awesome looking van on the inside. Great size, great condition, diesel heater full height pantry and the weights all work well.Really tidy. Someone will be very happy with this one.
Underside of floor	Good	
Suspension	Roller Rocker	
Wheel size	15"	
Tyres	LT235/75/R15	A bit of uneven wear- All roadworthy
Spare tyre- Location and condition	On Back Bumper	Good
Stabiliser legs	Good	
Last serviced	25/2/25	
Draw bar	Good	
Hitch type and condition	50mm Ball	Good
Gas bottles- in date/ condition	2 x 9kg	
Water tanks	2 x 95 litre	
Grey water tank	1	
Toolbox	No	
Front of caravan- Material and	Composite	Good
damage	NI -	
Front boot- any water ingress	No	
Door side of caravan- Material and damage	Composite	Good
Back of caravan- Material and damage	Composite	Good
Roadside of caravan- Material and damage	Composite	Good
Roof- Material and damage	Composite	Good
Solar panels- Size and number	2 x 170w	We have guessed that they are 170W we are not certain
Batteries- Number, size, type, visual condition	2 x 130AH	2 x Motor Att deep cycle 130AH
Mains battery charger	Yes	MW 3 stage switching
DC-DC charger	No	
Inverter	No	
Solar charge controller	Voltech	
Battery management system	None	
Awning- brand, condition, damage	Dometic	Small repair near sail track - overall good
External lights	Good	
External shower	No	
Rear view camera	Yes	

Entry door and wire door Curtain, Blind on entry door Windows Pillow Top Windows Good Fly wire Signs of water damage - in overhead cupboards Signs of water damage - in lower corners of walls Signs	Car kit for rear view camera	No	
Curtain / Blind on entry door		Good	
Mattress Pillow Top Good Windows Good Pily wire Good Fly wire Good Signs of water damage- in overhead cupboards Signs of water damage - upper corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in Overhead cupboards Signs of water dama		Curtain	Good
Mindows Good Blinds Good Signs of water damage - in overhead cupboards Signs of water damage - in lower curposor of walls Signs of water damage - in lower cupboards Signs of water damage - in lower cupboards Signs of water damage - in lower cupboards Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of w	-		
Blinds Good Fly wire Good Signs of water damage- in overhead cupboards Signs of water damage - upper corners of walls Signs of water damage - in lower cupboards Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - under lounge No overhead cupboards Signs of water damage - under lounge No lounge Internal lights Good Dometic Compressor Stove / Oven Good Swift			
Fly wire Signs of water damage- in overhead cupboards Signs of water damage - upper corners of walls Signs of water damage - in lower cupboards Signs of water damage - in lower cupboards Signs of water damage - in lower cupboards Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - under lounge Internal lights Good Air conditioner Good Sidney oven Good Swift Microwave Good Microwave Good Hot water service Good Shower Good Water pump Good Water pump Good Water pump Good Water pump Good Internal walls Good Internal walls Good Internal walls Good Internal filors Good Swift Good Cond Cond Cond Cond Cond Cond Cond C			
Signs of water damage- in overhead cupboards Signs of water damage - upper corners of walls Signs of water damage - in lower cupboards Signs of water damage - in lower cupboards Signs of water damage - in lower corners of walls Signs of water dam			
cupboards Signs of water damage - upper corners of walls Signs of water damage - in lower cupboards No Signs of water damage - in lower corners of walls No Signs of water damage - in lower corners of walls No Signs of water damage - in lower corners of walls No Signs of water damage - in lower corners of walls No Signs of water damage - under lounge No Internal lights Good Air conditioner Good Fridge Good Stove/ oven Good Microwave Good Toilet Good Hot water service Good Shower Good Washing machine Good Ensuite hatches Good Hatches Good Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Taps Good To an internal Good Good Tower cabinetry doors Good Radio Furion Good			
Signs of water damage - upper corners of walls Signs of water damage - in lower cupboards Signs of water damage - in lower cupboards Signs of water damage - in lower corners of walls Signs of water damage - in owerhead cupboards Signs of water damage - in owerhead cupboards Signs of water damage - under lounge No lounge Internal lights Good Belaire 3400 Internal lights Good Dometic Compressor Stove/ oven Good Swift	_		
Corners of walls Signs of water damage - in lower curpboards Signs of water damage - in lower corners of walls Signs of water damage - in lower corners of walls Signs of water damage - in No overhead cupboards Signs of water damage - under lounge Internal lights Good Belaire 3400 Fridge Good Dometic Compressor Stove/ oven Good Swift Microwave Good Swift Microwave Good Swift gas / electric Shower Good Water pump Good Dometic Front loader Ensuite hatches Good Internal walls Good Small crack under bedroom window RHS Internal floors Good Cood Cood Small crack under bedroom window RHS Internal floors Good Cood Cood Cood Cood Cood Cood Cood	-	No	
Signs of water damage - in lower cupboards Signs of water damage - in lower corners of walls Signs of water damage - in overhead cupboards Signs of water damage - in overhead cupboards Signs of water damage - in overhead cupboards Signs of water damage - under lounge Internal lights Good Air conditioner Good Sood Sover Good Microwave Good Toilet Good Hot water service Good Swift gas / electric Shower Good Water pump Good Water pump Good Water pump Good Hatches Good Internal floors Good Small crack under bedroom window RHS Internal floors Good Cood Cood Cood Cood Cood Cood Cood			
cupboards Signs of water damage - in lower corners of walls Signs of water damage - in overhead cupboards No overhead cupboards Signs of water damage - under lounge No overhead cupboards Internal lights Good Air conditioner Good Fridge Good Stove/ oven Good Microwave Good Toilet Good Hot water service Good Shower Good Washing machine Good Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Lounge Good Taps Good Toy OK TV OK TV antenna Good Radio Furion Good	Signs of water damage - in lower	No	
Signs of water damage - in overhead cupboards			
Signs of water damage - in overhead cupboards	Signs of water damage - in lower	No	
Overhead cupboards Signs of water damage - under lounge Internal lights Good Air conditioner Good Fridge Good Stove/ oven Good Microwave Good Toilet Good Hot water service Good Shower Good Washing machine Good Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Ensuite bench Good Lounge Good Internal floors Good Kitchen bench Good Lounge Good Lounge Good Lounge Good Table Good Lower cabinetry doors Good TV OK TV OK TV antenna Good			
Signs of water damage - under lounge No Internal lights Good Air conditioner Good Fridge Good Stove/ oven Good Microwave Good Toilet Good Hot water service Good Shower Good Washing machine Good Ensuite hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Tow OK TV OK TV antenna Good Radio Furion Good	Signs of water damage - in	No	
Internal lights Good Belaire 3400	overhead cupboards		
Internal lights Good Belaire 3400 Air conditioner Good Belaire 3400 Fridge Good Dometic Compressor Stove/ oven Good Swift Microwave Good Toilet Good Hot water service Good Swift gas / electric Shower Good Good Washing machine Good Dometic Front loader Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Lounge Good Tic cushion No Upper cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Signs of water damage - under	No	
Air conditioner Fridge Good Dometic Compressor Stove/ oven Good Swift Microwave Good Toilet Good Swift gas / electric Shower Good Water pump Good Dometic Front loader Ensuite hatches Good Small crack under bedroom window RHS Internal floors Good Tible Good Tic cushion Upper cabinetry doors Good TV antenna Good TV antenna Good Radio Furion Good Radio Furion Good Radio Furion Good Radio Furion Good Dometic Front loader	lounge		
Fridge Good Dometic Compressor Stove/ oven Good Swift Microwave Good Toilet Good Hot water service Good Swift gas / electric Shower Good Washing machine Good Ensuite hatches Good Internal walls Good Good Small crack under bedroom window RHS Internal floors Good Cood Good Good Good Good Good Good	Internal lights	Good	
Stove/ oven Good Swift Microwave Good Toilet Good Hot water service Good Shower Good Water pump Good Washing machine Good Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Lounge Good Tic cushion No Upper cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Air conditioner	Good	Belaire 3400
Microwave Good Toilet Good Hot water service Good Shower Good Water pump Good Washing machine Good Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Lounge Good Tic cushion No Upper cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Fridge	Good	Dometic Compressor
Toilet Good Swift gas / electric Shower Good Water pump Good Washing machine Good Dometic Front loader Ensuite hatches Good Internal walls Good Small crack under bedroom window RHS Internal floors Good Ensuite bench Good Tood Cood Cood Cood Cood Cood Cood C	Stove/ oven	Good	Swift
Hot water service Good Swift gas / electric Shower Good Water pump Good Dometic Front loader Ensuite hatches Good Internal walls Good Small crack under bedroom window RHS Internal floors Good Ensuite bench Good Table Good Good Cood Good Tit cushion No Upper cabinetry doors Good Taps Good Too Kitchen Good Cood Good Cood Good Cood Cood Good Cood Good Cood C	Microwave	Good	
Shower Good Water pump Good Washing machine Good Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Toilet	Good	
Water pump Good Washing machine Good Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Lounge Good Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good TV OK TV antenna Good Radio Furion Good	Hot water service	Good	Swift gas / electric
Washing machine Good Dometic Front loader Ensuite hatches Good Hatches Good Internal walls Good Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Lounge Good Upper cabinetry doors Good Lower cabinetry doors Good TV OK TV antenna Good Radio Furion Good	Shower	Good	
Ensuite hatches Good Hatches Good Internal walls Good Small crack under bedroom window RHS Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Furion Good		Good	
Hatches Good Internal walls Good Small crack under bedroom window RHS Internal floors Good Kitchen bench Good Ensuite bench Good Cuunge Good Tic cushion No Upper cabinetry doors Good Cuwer cabinetry doors Good Taps Good TV OK TV antenna Good Furion Good Furion Good Cude To Cook Turner Good Cude To Cook Turner Good Tro Cook Turner Good Cude To Cook Turner Good Cude Turner Good Tro Cook Turner Good Furion Good Furion Good		Good	Dometic Front loader
Internal walls Good Small crack under bedroom window RHS Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Ensuite hatches	Good	
Internal floors Good Kitchen bench Good Ensuite bench Good Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Hatches	Good	
Kitchen bench Good Ensuite bench Good Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good		Good	Small crack under bedroom window RHS
Ensuite bench Good Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Internal floors	Good	
Table Good Lounge Good Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Kitchen bench	Good	
Lounge Good Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Ensuite bench	Good	
Tic cushion No Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Table	Good	
Upper cabinetry doors Good Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Lounge	Good	
Lower cabinetry doors Good Taps Good TV OK TV antenna Good Radio Furion Good	Tic cushion	No	
Taps Good TV OK TV antenna Good Radio Furion Good	Upper cabinetry doors	Good	
TV OK TV antenna Good Radio Furion Good	Lower cabinetry doors	Good	
TV antenna Good Radio Furion Good	Taps	Good	
Radio Furion Good	TV	ОК	
	TV antenna	Good	
42 (Radio	Furion	Good
12V tans One Sirrocco	12v fans	One	Sirrocco

Note: Has diesel heater - Eberspacher

COMPLIANCE PLATE WEIGHTS

ATM: 3200 kg TARE: 2676 kg

BALL WEIGHTS: 144 kg