

Make: Jayco

Model: Starcraft

Registration (REGO): V77080

VIN: 6AM000000DIR67780

Chassis Number: _____

Year: 12/2013



CONDITION REPORT

	Type	Comments
Manager's comments		There is a small sign of water ingress around the wind up antenna. It has been resealed and is in good condition. Under 2,000KG loaded, diesel heater, air conditioner, great clearance and is in good condition. A good one!
Underside of floor	Good	
Suspension	Leaf Spring	
Wheel size	15"	
Tyres	New	
Spare tyre- Location and condition	Rear	Not new - reasonable condition
Stabiliser legs	Good	
Last serviced	23/6/25	
Draw bar	Good	
Hitch type and condition	50mm Ball	Good
Gas bottles- in date/ condition	Good	2 x 9kg
Water tanks	2 x 75L	
Grey water tank	No	
Toolbox	No	
Front of caravan- Material and damage	Fiberglass - Good	
Front boot- any water ingress	No	
Door side of caravan- Material and damage	Aluminium	Some small dents from normal use
Back of caravan- Material and damage	Fiberglass	Good
Roadside of caravan- Material and damage	Aluminium	Small dents from normal use
Roof- Material and damage	FiberGlass	OK
Solar panels- Size and number	1	
Batteries- Number, size, type, visual condition	1	New 120AH AGM battery
Mains battery charger	Yes	
DC-DC charger	N/A	
Inverter	N/A	
Solar charge controller	Solar 30	
Battery management system	No	
Awning- brand, condition, damage	Good	Brand new canvas
External lights	Good	
External shower	No	
Rear view camera	No	
Car kit for rear view camera	No	

Entry door and wire door	Good	
Curtain/ Blind on entry door	Curtain	
Mattress	Good	
Windows	Good	
Blinds	Good	
Fly wire	Good	
Signs of water damage- in overhead cupboards	No	
Signs of water damage - upper corners of walls	No	
Signs of water damage - in lower cupboards	No	
Signs of water damage - in lower corners of walls	No	
Signs of water damage - in bedside cupboards		
Signs of water damage - under lounge	No	
Internal lights	Good	
Air conditioner	Yes	
Fridge	Yes	
Stove/ oven	Yes	
Microwave	Yes	
Toilet	Yes	
Hot water service	Yes	
Shower	Yes	
Water pump	Good	
Washing machine	Good	
Ensuite hatches	Good	
Hatches	Pop top	
Internal walls	Good	Some pimpling just above toilet - It appears to be the paper coating deteriorating. No sign of water ingress or damage.
Internal floors	Good	
Kitchen bench	Good	
Ensuite bench	Good	
Table	Good	
Lounge	Good	
Tic cushion	NA	
Upper cabinetry doors	Good	
Lower cabinetry doors	Good	
Taps	Good	
TV	Yes	
TV antenna	OK	
Radio	Good	
12v fans	N/A	

COMPLIANCE PLATE WEIGHTS

ATM: 1987 kg

TARE: 1612 kg

BALL WEIGHTS: 196 kg