

Make: Atlantic

Model: Murcheson

Registration (REGO): _____

VIN: _____

Chassis Number: ATL1065

Year: 2016



CONDITION REPORT

	Type	Comments
Underside of floor		Okay
Suspension	Rocker roller	good
Wheel size	15"	
Tyres		Okay- rear drivers needs replacing
Spare tyre- Location and condition	Rear	Good
Stabiliser legs	Manual	Good
Last serviced	?	
Draw bar		Good
Hitch type and condition	Ball hitch	Good
Gas bottles- in date/ condition		
Water tanks		2 x 95Ltr water tanks
Grey water tank		1 x 95Ltr Grey water tank
Toolbox	No	
Front of caravan- Material and damage		
Front boot- any water ingress	Galvanised	No signs of water
Door side of caravan- Material and damage	Cladding	Has slight damage – Picnic table broken
Back of caravan- Material and damage	composite	Dings and scratches
Roadside of caravan- Material and damage	Cladding	Has scratches
Roof- Material and damage		Has wear
Solar panels- Size and number		2 x 120W solar panels
Batteries- Number, size, type, visual condition		2 x 100amp AGM, good
Mains battery charger		Working
DC-DC charger	N/A	
Inverter	N/A	
Solar charge controller		Working
Battery management system		Working
Awning- brand, condition, damage	Dometic	Good condition
External lights		Good
External shower	N/A	

Rear view camera	Safety Dave	
Car kit for rear view camera	N/A	
Entry door and wire door	Camec	Okay has some scratches
Curtain/ Blind on entry door		Okay
Mattress	N/A	
Windows	Dometic flat blind	Heavy travel scratches
Blinds		Some okay some damaged
Fly wire		Some okay some damaged
Signs of water damage- in overhead cupboards		Yes
Signs of water damage - upper corners of walls		Yes
Signs of water damage - in lower cupboards		No
Signs of water damage - in lower corners of walls		No
Signs of water damage - in overhead cupboards		No
Signs of water damage - under lounge		No
Internal lights		Okay
Air conditioner	IBIS 3	Okay
Fridge	Thetford	3 way, okay condition
Stove/ oven	Thetford	Okay
Microwave	Sphere	Okay
Toilet	Thetford	Ceramic bowl
Hot water service		
Shower		Okay
Water pump	Yes	Working
Washing machine	Camec	4Kg front loader
Ensuite hatches		Okay
Hatches		Blind damaged
Internal walls		Stained with water
Internal floors		Okay
Kitchen bench		Okay with marks
Ensuite bench		Okay with marks
Table	Nuova mappa table leg	Okay with marks
Lounge		Marks
Tic cushion		N/A
Upper cabinetry doors		All working- 1 missing handle
Lower cabinetry doors		All working- 1 missing handle
Taps		All working

TV	N/A	
TV antenna		Windup TV antenna
Radio	NCE	
12v fans	N/A	

COMPLIANCE PLATE WEIGHTS
ATM: 2990KG
TARE: 2490KG
BALL WEIGHTS: 230KG