Make: Concept Model: Belmont

Registration (REGO): \_\_\_\_\_\_ VIN: CJHCONCEPAS000605

Chassis Number: C3540 Year: 2016



## **CONDITION REPORT**

	Туре	Comments
Underside of floor	Wood	Good condition
Suspension	Rocker Roller	Surface rust
Wheel size	14"	
Tyres	LT	Okay
Spare tyre- Location and condition	Rear bumber	Okay
Stabiliser legs	Manual	Okay condition- 1 rear leg has a crack in the foot
Last serviced	?	
Draw bar		Surface rust
Hitch type and condition	Ball hitch	Okay
Gas bottles- in date/ condition		
Water tanks	2	2 x 80Ltr
Grey water tank	N/A	
Toolbox	N/A	
Front of caravan- Material and damage		<ul> <li>Front boot fabric peeling off</li> <li>Front of van rock dings</li> </ul>
Front boot- any water ingress	Galvanised	Yes
Door side of caravan- Material and damage	Cladding	Decent condition with some marks
Back of caravan- Material and damage	Cladding	Decent condition with some marks
Roadside of caravan- Material and damage	Cladding	Decent condition with some marks
Roof- Material and damage		3 piece aluminium
Solar panels- Size and number	N/A	
Batteries- Number, size, type, visual condition	1	1 x 100amp AGM, good condition
Mains battery charger	Ctek	Multi X5 25000
DC-DC charger	N/A	
Inverter	N/A	
Solar charge controller	N/A	
Battery management system	N/A	
Awning- brand, condition, damage	Dometic	15FT
External lights		Not working
External shower	N/A	
Rear view camera	N/A	
Car kit for rear view camera	N/A	

Entry door and wire door	Camec	Good condtion
Curtain/ Blind on entry door		Good condition
Mattress	Queen	Good
Windows		Good condition with light travel scratches
Blinds		Good condition
Fly wire		Good condition
Signs of water damage- in overhead		Severe water damage in front wall and with rot
cupboards		<b>g</b>
Signs of water damage - upper		Yes
corners of walls		
Signs of water damage - in lower		Yes at front of van
cupboards		
Signs of water damage - in lower corners of walls		Yes in ensuite
Signs of water damage - in		Yes
overhead cupboards		163
Signs of water damage - under		No
lounge		
Internal lights		Visually look okay
Air conditioner	Air V Carrier	
Fridge	Dometic	Single door fridge/ Freezer, 3 way
Stove/ oven	Spinflo	Grill/ cooktop, good condition
Microwave	LG	Good condition
Toilet	Thetford	
	casette	
Hot water service	Truma	
Hot water service Shower	Truma	Good
Shower Water pump	Truma Yes	Good
Shower		Good
Shower Water pump	Yes	Good With electric fans
Shower Water pump Washing machine	Yes N/A	
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls	Yes N/A	With electric fans
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors	Yes N/A	With electric fans 4 seasons
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls	Yes N/A	With electric fans 4 seasons Water stains
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors	Yes N/A	With electric fans 4 seasons Water stains Good condtion
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors  Kitchen bench	Yes N/A	With electric fans 4 seasons Water stains Good condition Good condition
Shower  Water pump  Washing machine Ensuite hatches  Hatches Internal walls Internal floors  Kitchen bench Ensuite bench	Yes N/A	With electric fans 4 seasons Water stains Good condition Good condition Good condition
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors  Kitchen bench  Ensuite bench  Table	Yes N/A	With electric fans 4 seasons Water stains Good condition Good condition Good condition Good condition
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors  Kitchen bench  Ensuite bench  Table  Lounge  Tic cushion  Upper cabinetry doors	Yes N/A 2	With electric fans 4 seasons Water stains Good condition Good condition Good condition Good condition
Shower Water pump Washing machine Ensuite hatches Hatches Internal walls Internal floors Kitchen bench Ensuite bench Table Lounge Tic cushion	Yes N/A 2	With electric fans 4 seasons Water stains Good condition Good condition Good condition Good condition Good condition Good condition
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors  Kitchen bench  Ensuite bench  Table  Lounge  Tic cushion  Upper cabinetry doors	Yes N/A 2	With electric fans 4 seasons Water stains Good condition
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors  Kitchen bench  Ensuite bench  Table  Lounge  Tic cushion  Upper cabinetry doors  Lower cabinetry doors	Yes N/A 2	With electric fans 4 seasons Water stains Good condition Good, all working Good, all working
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors  Kitchen bench  Ensuite bench  Table  Lounge  Tic cushion  Upper cabinetry doors  Lower cabinetry doors  Taps	Yes N/A 2	With electric fans 4 seasons Water stains Good condition Good condition Good condition Good condition Good condition Good condition Good, all working Good, all working Good
Shower  Water pump  Washing machine  Ensuite hatches  Hatches  Internal walls  Internal floors  Kitchen bench  Ensuite bench  Table  Lounge  Tic cushion  Upper cabinetry doors  Lower cabinetry doors  Taps  TV	Yes N/A 2 N/A	With electric fans 4 seasons Water stains Good condition Good condition Good condition Good condition Good condition Good condition Good, all working Good, all working Good Good

COMPLIANCE PLATE WEIGHTS

ATM:2145KG TARE:1754KG

BALL WEIGHTS:190KG