

Make: Austrack

Model: GIB 14

Registration (REGO): 314-70C

VIN: LB914DA2XP0KP5707

Chassis Number:

Year:



## CONDITION REPORT

|                                                 | Type             | Comments                                             |
|-------------------------------------------------|------------------|------------------------------------------------------|
| Underside of floor                              | Aluminium Coated | Good                                                 |
| Suspension                                      |                  | Austuff off road with pedders 4x4 foam cell shockers |
| Wheel size                                      | 16"              |                                                      |
| Tyres                                           |                  | LT26575R16 Goodride Radis M/T - Good                 |
| Spare tyre- Location and condition              |                  | 2 new on rear                                        |
| Stabiliser legs                                 |                  | Good                                                 |
| Last serviced                                   |                  |                                                      |
| Draw bar                                        |                  | Good                                                 |
| Hitch type and condition                        |                  | McHitch 3.5T Full off-road coupling                  |
| Gas bottles- in date/ condition                 |                  | Both out of date. 1989 & 2009                        |
| Water tanks                                     | 2 x 120L         |                                                      |
| Grey water tank                                 | 1 x 80L          |                                                      |
| Toolbox                                         |                  | With gas bottles                                     |
| Front of caravan- Material and damage           |                  | Aluminium Composite                                  |
| Front boot- any water ingress                   |                  | No                                                   |
| Door side of caravan- Material and damage       |                  | Aluminium Composite                                  |
| Back of caravan- Material and damage            |                  | Aluminium Composite                                  |
| Roadside of caravan- Material and damage        |                  | Aluminium Composite                                  |
| Roof- Material and damage                       |                  | Reinforced Aluminium Composite                       |
| Solar panels- Size and number                   |                  | 6 x 100W blankets                                    |
| Batteries- Number, size, type, visual condition |                  | Renogy 12V 100AH lithium x 4                         |
| Mains battery charger                           |                  | Redarc Manager 30 BMS 123053                         |
| DC-DC charger                                   |                  |                                                      |
| Inverter                                        | Redarc           | 2000W                                                |
| Solar charge controller                         |                  | Inc Redarc Manager 30                                |
| Battery management system                       |                  | Redarc Manager 30                                    |
| Awning- brand, condition, damage                | Hailinge         | Good                                                 |
| External lights                                 | Good             |                                                      |
| External shower                                 | Yes              |                                                      |
| Rear view camera                                | Yes              |                                                      |
| Car kit for rear view camera                    | No               | Wireless, no monitor                                 |
| Entry door and wire door                        | Good             |                                                      |
| Curtain/ Blind on entry door                    | Curtain          |                                                      |
| Mattress                                        | Good             |                                                      |
| Windows                                         | All Good         |                                                      |
| Blinds                                          | All Good         |                                                      |

|                                                          |                     |         |
|----------------------------------------------------------|---------------------|---------|
| <b>Fly wire</b>                                          | All Good            |         |
| <b>Signs of water damage- in overhead cupboards</b>      | No                  |         |
| <b>Signs of water damage - upper corners of walls</b>    | No                  |         |
| <b>Signs of water damage - in lower cupboards</b>        | No                  |         |
| <b>Signs of water damage - in lower corners of walls</b> | No                  |         |
| <b>Signs of water damage - in overhead cupboards</b>     | No                  |         |
| <b>Signs of water damage - under lounge</b>              | No                  |         |
| <b>Internal lights</b>                                   | Good                |         |
| <b>Air conditioner</b>                                   | Dometic             | Good    |
| <b>Fridge</b>                                            | Thetford Compressor | Good    |
| <b>Stove/ oven</b>                                       | Thetford            | Good    |
| <b>Microwave</b>                                         | Moborv              | Good    |
| <b>Toilet</b>                                            | Dometic             | Good    |
| <b>Hot water service</b>                                 | Truma               | Good    |
| <b>Shower</b>                                            | Good                |         |
| <b>Water pump</b>                                        | Seaflo              | Good    |
| <b>Washing machine</b>                                   | Moborv              | Good    |
| <b>Ensuite hatches</b>                                   | Good                |         |
| <b>Hatches</b>                                           | Good                |         |
| <b>Internal walls</b>                                    | Good                |         |
| <b>Internal floors</b>                                   | Good                |         |
| <b>Kitchen bench</b>                                     | Good                |         |
| <b>Ensuite bench</b>                                     | Good                |         |
| <b>Table</b>                                             | Good                |         |
| <b>Lounge</b>                                            | Good                |         |
| <b>Tic cushion</b>                                       | Good                |         |
| <b>Upper cabinetry doors</b>                             | Good                |         |
| <b>Lower cabinetry doors</b>                             | Good                |         |
| <b>Taps</b>                                              | Good                |         |
| <b>TV</b>                                                | Good                | No name |
| <b>TV antenna</b>                                        | None                |         |
| <b>Radio</b>                                             | Good                |         |
| <b>12v fans</b>                                          | Good                |         |
| <b>Outdoor kitchen</b>                                   | Good                |         |
| <b>Fridge in front boot</b>                              | Good                |         |

#### COMPLIANCE PLATE WEIGHTS

ATM: 3000 kg

TARE: 2400 kg

BALL WEIGHTS: kg