

Make: Jayco

Model: Swan

Registration (REGO): V54 157

VIN: 6AM000000B1N31001

Chassis Number: N31001

Year: 12/11



CONDITION REPORT

	Type	Comments
Underside of floor	Wood	Some water staining
Suspension	Roller rocker single axel	Slight rust
Wheel size	14"	185R14 102/100Q8PRLT
Tyres		OK
Spare tyre- Location and condition	Bumper	
Stabiliser legs	Drop wind	All work
Last serviced		
Draw bar		Looks good
Hitch type and condition	Ball recessed	Some rust, normal
Gas bottles- in date/ condition	1 x 8.5kg	Not in date. 6/11
Water tanks	1	Maybe 95L
Grey water tank	No	
Toolbox	No	
Front of caravan- Material and damage	Fibreglass white & cloth. Painted grey	One crack, hinge point on front boot damaged. Front panel few cracks by rivets. Slight fade & chips in grey, decals peeling
Front boot- any water ingress	No	
Door side of caravan- Material and damage	Fibreglass white & cloth.	Light scratches A few cuts in flyscreen left of door
Back of caravan- Material and damage	Fibreglass white & cloth.	Few scratches on wheel cover. Straps of bagged awning broken
Roadside of caravan- Material and damage	Fibreglass white & cloth.	One cut in flyscreen. Good
Roof- Material and damage	Fibreglass	Silicone hard and cracked
Solar panels- Size and number	No	
Batteries- Number, size, type, visual condition	No	Battery box empty
Mains battery charger	Unknown brand	Has fuses inbuilt
DC-DC charger	N/A	
Inverter	N/A	
Solar charge controller	N/A	
Battery management system	N/A	
Awning- brand, condition, damage	N/A	
External lights		Needs fixing
External shower	N/A	
Rear view camera	N/A	

Car kit for rear view camera	N/A	
Entry door and wire door	Fold	OK. Window has slight damage
Curtain/ Blind on entry door	Curtain	
Mattress	2 – Pushout	OK
Windows	Clear plastic with zips	Some fading
Blinds	Curtains	Good
Fly wire		Few small cuts
Signs of water damage- in overhead cupboards	N/A	
Signs of water damage - upper corners of walls	No	
Signs of water damage - in lower cupboards	No	
Signs of water damage - in lower corners of walls	No	
Signs of water damage - in overhead cupboards	N/A	
Signs of water damage - under lounge	No	
Internal lights		All work
Air conditioner	N/A	
Fridge	Dometic	3 way
Stove/ oven	Unknown brand	Works
Microwave	Sphere	Works
Toilet	N/A	
Hot water service	N/A	
Shower	N/A	
Water pump	Hand	
Washing machine	N/A	
Ensuite hatches	N/A	
Hatches		Good, inside base has a crack
Internal walls	Cloth	Few stains, slight wear. Sunlight coming through rear bed, front drivers corner needs fixing
Internal floors		Good
Kitchen bench		Slight scratches & one ding
Ensuite bench	N/A	
Table		Good, folds into bed
Lounge		Good
Tic cushion	Yes	
Upper cabinetry doors	N/A	
Lower cabinetry doors		Some handles need adjusting
Taps		Mains & hand pump
TV	N/A	
TV antenna		Normal set up
Radio	N/A	
12v fans	N/A	

COMPLIANCE PLATE WEIGHTS

ATM: 1389 kg

TARE: 1089 kg

BALL WEIGHTS: 111 kg